

10





**FIG - 1A**

FIG - 2AFIG - 1BFIG - 2B




FIG -3A

FIG - 3B

A hand-drawn diagram of a stepped profile. The profile consists of three horizontal steps. The first two steps have a height of 30, and the third step has a height of 12. The total height of the profile is 28. The diagram is oriented vertically.

FIG - 3C







FIG - 9






FIG - 5B






FIG - 6B










FIG - 8AFIG - 8B

32

FIG - 10B



32

FIG - 10A

